

APPENDIX - XIII

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. 05/WSM/NLG/2023

Dated: 22.5.2023

It is certified that an inspection team headed by K. Govardhan Chary Sample Taker
(Name of Officers with designation) from B. Prabhakar Sample Taker

(Name of Department/ Office) inspected the Water Quality Monitoring Lab, Nalgonda

(Name & Address of the school) on 17.5.2023 (date of inspection) and found that the
the Nalgonda Public School (Name of school) has safe drinking water
facilities for the students and members of staff of the institution and is maintaining the hygienic
sanitation condition in the school building & the campus as per norms prescribed by the Central/
State/ U.T. Govt.

The above is valid for a period of 6 months

Signature with Seal: K. Vimala Kumari

Name : K. Vimala Kumari

Designation : Junior Analyst

Name & Address of the Office / Department: Water Quality Monitoring Lab, Nalgonda
Junior Analyst
Water Quality Monitoring Lab, Nalgonda
Old Municipal Colony, Nalgonda

To

the Principal

the Nalgonda Public School, Nalgonda

(Name & Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

[Signature]
President & Correspondent
THE NALGONDA PUBLIC SCHOOL
NALGONDA.

[Signature]
PRINCIPAL
THE NALGONDA PUBLIC SCHOOL
6-2-907, Meerbagh Colony, NALGONDA

WATER QUALITY MONITORING LAB


Directorate of I.P.M., P.H. Labs, Food (H) Administration, Narayanaguda, Hyd.
Old Municipal Complex, Nalgonda - 508 001.

REPORT OF BACTERIOLOGICAL ANALYSIS OF WATER


Sample From : the principal, the Nalgonda public school, 6-2-907
Meerbagh Colony Nalgonda.
Collected by : K. Govardhana Chary ST & B. Prabhakar ST
Collected on : 17.5.2023. Received on : 17.5.23 Reported On : 22.5.2023

Lab Ref. No.	Source	Exact location	Residual Chlorine mg per liter	Total Coliform Bacteria (MPN Index) per 100 ml.	Faecal Coliform Bacteria per 100ml	Esch. Coli. per 100ml
348	Krishna Water	Tap at sump	-	NT	-	-
850	purified Water	Tap at through cooler point	-	NT	-	-

Remarks :- The above water samples are bacteriologically satisfactory for drinking purpose.


President & Correspondent
THE NALGONDA PUBLIC SCHOOL
NALGONDA.


PRINCIPAL
THE NALGONDA PUBLIC SCHOOL
6-2-907, Meerbagh Colony, NALGONDA.


Junior Analyst
Water Quality Monitoring Lab
Old Municipal Complex.
NALGONDA.
Water Quality Monitoring Lab

WATER QUALITY MONITORING LAB

Directorate of I.P.M., P.H. Labs, Food (H) Administration, Narayanaguda, Hyd.
Old Municipal Complex, Nalgonda - 508 001.

REPORT OF PHYSICO CHEMICAL ANALYSIS OF WATER

Sample from : the principal, the Nalgonda public school, 6-2-907
 District : Nalgonda. Meerbagh Colony Nalgonda.
 Collected by : K. Govardhana chary es & B. prabhakar es
 Collected on : 17.5.2023 Received On: 17.5.2023 Reported on: 22.5.2023
 Lab Ref. No. : 1849 1851
 Source of Water : Krishna Water pumped Water
 Papat Sump RESULTS

PHYSICAL PARAMETERS			Drinking water - Specification As per IS 10500 : 2012	
			Requirement, (Acceptable limit)	permissible limit the absence of alternate source
Colour	colourless	colourless	5	15
Turbidity (NTUS)	0.2	0.1	1	5
Odour	un-objectionable, -do-		Un-Objectionable	Un-Objectionable'
pH at 'C	8.0	7.8	6.5 - 8.5	No relaxation
Electrical Conductivity at 25°C (MicroMhos/CM)	580	100		
Total Dissolved solids mg/L, Max	377	65	500	2000

CHEMICAL PARAMETERS FOLLOWING RESULTS IN MILLIGRAMS PER LITRE

Alkalinity (as CaCO ₃)	nil	nil		
Phenolphthalein				
Total Alkalinity, Max	80	24	200	600
Total Hardness (as CaCO ₃), Max	180	40	200	600
Calcium Hardness as (CaCO ₃), Max	100	24		
Ammonical-Nitrogen (NH ₃ -N)	nil	nil		
Nitrite as (as N)	nil	nil		
Nitrate (as N)	-	-		
Chloride (as Cl), Max	88	24	200	1000
Fluoride (as F), Max	0.5	0.2	1.0	1.5
Iron (as Fe), Max	nil	nil	0.3	No relaxation

Remarks : All the analysed chemical parameters of the above water samples are within the permissible limits. physico-chemically satisfactory for drinking purpose.

[Signature]
 President & Correspondent
 THE NALGONDA PUBLIC SCHOOL
 NALGONDA

[Signature]
 PRINCIPAL
 Junior Analyst
 THE NALGONDA PUBLIC SCHOOL
 Meerbagh Colony, NALGONDA
 Water Quality Monitoring Lab

OFFICE OF THE MUNICIPAL COUNCIL:: NALGONDA

No.F1/2618/2023-24

Date: 01.06.2023

SANITARY CERTIFICATE

This is to certify that **The Nalgonda Public School** located in premises **H.No.6-2-907, Meerbagh Colony, Nalgonda** is provided with proper accommodation, ventilation, lighting, water supply and sanitation in the premises, which are found to be satisfactory.

Hence, this "Sanitary Certificate" is issued, subject to condition that, if any complaints received in future, the same will be cancelled without assigning any notices and further action will be taken as per rules.

[Signature]
Commissioner

Nalgonda Municipality

[Signature] 1/6/23 *[Signature]* *[Signature]*
1/6

To
The Principal,
The Nalgonda Public School,
H.No. 6-2-907,
Meerbagh Colony,
Nalgonda.

[Signature]
President & Correspondent
THE NALGONDA PUBLIC SCHOOL
NALGONDA.

[Signature]
PRINCIPAL
THE NALGONDA PUBLIC SCHOOL
6-2-907, Meerbagh Colony, NALGONDA.